

Needs flashing that requires partial (potentially dangerous) disassembly, or possibly new parts.

Possible documented fix: <https://gr5.org/unbricking/>

