

Currently we get slow wall leaks, as though walls are "weeping" on NE and SE walls.

NE wall is not shared. Leaks are likely due to grading of soil at building perimeter, or possibly through building wall, either via cracks or bad mortar at some height, or faults at roof via rundown.

SE wall is not shared towards rear portion, and likely has same issue as NE wall.

SE *is* shared further towards woodward, leaks may be from unmaintained entrance to basement space of neighboring building.

